Technical Newsletter

#tnl2018-0014e # 1 / 1



DFG8540/DFS8960 Maintenance Manual Request for Correction of Errors in the Part Numbers for the Robot Picks

Purpose of this Technical Newsletter

We have found some errors in the part numbers for the robot picks described in the Maintenance Manuals for the DFG8540 and DFS8960. Please check the details and correct them.

Applicable Maintenance Manual

Applicable model	Part No. in the Maintenance Manual		
DFG8540	English	UJLSMEH002A, UJLSMEH002M, UJLSMEH002P, UJLSMEH002S, UJLSMEH002T, UJLSMEH002U, UJLSMEH004A, UJLSMEH004B, UJLSMEH004C, UJLSMEH004D, UJLSMEH004E, UJLSMEH004F, UJLSMEH004G, UJLSMEH004H, UJLSMEH004I	
	Japanese	UJLSMJH002A, UJLSMJH002M, UJLSMJH002P, UJLSMJH002S, UJLSMJH002T, UJLSMJH002U, UJLSMJH004A, UJLSMJH004B, UJLSMJH004C, UJLSMJH004D, UJLSMJH004E, UJLSMJH004F, UJLSMJH004G, UJLSMJH004H, UJLSMJH004I	
DFS8960	English	UPWSMEH001A, UPWSMEH001B	
	Japanese	UPWSMJH001A, UPWSMJH001B	

Correction details

[DFG8540]

Item		Part No. [wrong]	Part No. [correct]
Robot pick	For 4" to 8"	LJLL-910218-1	FJLL-910005-4
	diameter wafers	LJLL-910218-0	
	(standard)	MOJLL218B	
		MOJLL218	
	For 6" to 8"	LJLL-910222-1	FJLL-910006-4
	diameter wafers	LJLL-910222-0	
		MOJLL222A	
		MOJLL222	
	Dedicated for 8"	LJLL-910224-1	FJLL-910008-5
	diameter	LJLL-910224-0	
	wafers	MOJLL224A	
		MOJLL224	

[DFS8960]

Item	Part No. [wrong]	Part No. [correct]
Robot pick	LJSL-910068-2	FJSL-910003-5
For 8"/12" diameter workpieces (standard)		

Inquiries

Please contact your local DISCO sales representative or customer engineer if you have any questions regarding this matter.