

Change in Color of Filter (Periodic Replacement Part) Installed in Air Unit

Purpose of this Technical Newsletter


Since production of the 0.01 μm filter installed in the air unit has been discontinued, it has been replaced with a successor product. As a result, the color of filters shipped from April 2018 onward has changed from red to white, and there may be cases where they differ from the details indicated in the instruction manual. We would like to take this opportunity to report the details of the change, as well as apologizing for the delay in notifying you.

Applicable model

DFD6750, EAD6750, DFD6755
DFG8340, DFG8360, DTG8440, DGP8760

Change details

	Before change	After change
DISCO Part ID	FILTER LKJV-920002-0	FILTER LKJV-920002-1
Color	Red	White



- Only the 0.01 μm filter for coalescing has changed. The color of the 5 μm filter for the regulator has not changed.
- There is no difference in the filtration performance or installation method for the filter before and after the change.

Request

In some cases, the filter color is indicated as "red" in the replacement procedure in the maintenance manual. We kindly request that you read this as "white" instead.

Inquiries

Please contact your local DISCO sales representative or customer engineer if you have any questions regarding this matter.