Technical Newsletter



#tnl2016-0013e # 1 / 1

Change the Load Sensor Installed in the DGP8761

Announcement


We change the load sensor installed in the DGP8761 and its relevant parts. From February 2016, any load sensors installed in the machines to be shipped are replaced by new ones in order.

Applicable model:

DGP8761 Dry polish specification

DGP8761 Poligrind specification

- There are no changes in the features and performance.
- The appearance of the amplifier and the connection method are different.



• For the load sensor, amplifier, mounting bracket, and cable, it is impossible to use existingtype ones and new-type ones in combination. For the parts relevant to the load sensor, use them in the following combination.

Product name	Part No. (existing-type)	Part No. (new type)
Load sensor	DBF9135B301-1	DBF9135BQ01-0
Amplifier	DBF5038A302-0	DBF5073A302-0
Mounting bracket	LNNZ-010067-2	LNNZ-010251-0
Cable	EKJJ-910131-2	ENNJ-010263-0
	ENNJ-010091-0	

Inquiries

Please contact your local DISCO sales representative or DISCO service office if you have any questions regarding this matter.